<u> TABLE – 2</u>

SAFETY DISTANCE

Safety distances to be observed in a factory licensed under Explosives Rules for manufacture of Sparklers only Distances are in metres

Sr.No	Description of shed	Mixing shed	Dipping shed	Drying platform	Packing shed	Empty frames shed	Raw materials store	Outside safety distance	Quantity explosives Kgs
1	Mixing shed	6	6	9	9	15	15	15	50
2	Dipping shed	6	6	3	9	15	15	15	200
3	Drying Platform	9	3	3	9	15	15	15	200
4	Packing shed	9	9	9	9	15	15	15	200